

ABSTRACT

An apparatus for measuring contact current includes data acquisition circuitry with at least two sensor contacts to measure the voltage drop across an animal or human body. A portable data processing unit is connected to the data acquisition
5 circuitry to process the voltage data to produce current flow data.

10
15
20
25
30
35
40
45
50
55
60
65
70
75
80
85
90
95
100